

MPEC projects approved in FY16

Project Number	Amount	Project name	Project Description	MPEC Contingency
September				
P790389	\$ 40,870.42	Welcome Center Compressor replacement Texas Learning and Computational Center Annex	Replace Damaged compressor and Sensors on Welcome Center Chiller	FY15
P790390	\$ 15,582.25	Roof repair	Leaking Roof poses threat to operation of UIT servers.	FY15
P790391	\$ 47,216.00	SR2 Air Compressor addition	Add a new compressor and tie into building automation	FY15
P790392	\$ 5,759.83	Hilton Grease Spill 2014 SFMO Findings - Fire rated door/frame	Emergency spill response of grease trap due to container rust Address lack of fire rating door/frame labeling at various stairways	FY15
P790393	\$ 5,830.00	labelling	at MD Anderson Library.	FY15
P790394 P790395	\$ 11,565.40	Pharmacy TMC Leak	Remediation and repair of two rooms flooded by damaged pipe.	FY13
P790396	\$ 33,000.00	FY16 CRDM E&G Window Repair	To be used as needed to repair damaged windows due to building settlement, vandalism, flying projectiles etc.	FY15
P790397	\$ 23,774.74	Health & Biomed Repair Fire Pump Controller	Repair controller and emergency power transfer switch so in the event of power loss the pump will continue operating	FY15
P790398	\$ 8,240.00	SERC Roof Access	To design and install new gate and barrier to prevent unauthorized roof access	FY15
P790399	\$ 30,525.00	Wortham Theater Heat Exchanger replacement	To replace existing hot water heat exchanger	FY15
P790400	\$ 49,797.72	Campus Wide JACE Integration	Integrate 12 JACES and communications cards for 11 buildings	FY15
P790401	\$ 4,729.03	Emergency Sanitary Leak at Hilton Garage	Remove existing leaking cast iron tee and replace	FY15
P790402	\$ 19,210.36	Emergency Water Leak at Moody Tower South	Replace broken ductile pipe	FY15
P790398 increase	\$ 15,307.25	SERC Roof Access	Construction and installation of Gate and Barrier	FY15

MPEC projects approved in FY16

Project Number	Amount	Project name	Project Description	MPEC Contingency
October				
P790120 increase	\$ 110,000.00	SR1 Exterior Façade Study	Provide Comprehensive review and exploratory investigation to SR1 façade.	FY15
P790403	\$ 24,380.32	CRC ADA Ramp replacement	Removal of old wooden ramp and replace with polymer planking and needed hardware to meet ADA Specifications	FY12
P790404	\$ 19,376.59	Health and Biomed Harmonic Logic Boards	Replace boards in chillers to protect electronic circuitry.	FY12
P790405	\$ 8,128.38	HSC Fire Alarm system design	To design fire alarm system at the University of Houston Science Center	FY15
P790406	\$ 33,500.00	Coastal Center minor renovation	Minor renovations including painting, ceiling tile replacement, install smoke detectors, replace doors	FY14
P790355 Increase	\$ 19,906.00	Hilton Grease Trap replacement	Demo existing trap and install new tank and grease trap	FY14
P790407	\$ 17,740.97	Hilton Hotel Domestic Water Pump	Replace domestic pumps with VFD system to prevent overheating of water.	FY14
P790408				
P790409	\$ 54,915.46	Optometry Building Elevator Hydraulic Cylinder replacement	Optometry Pubic Elevator #2 requires a cylinder to be replace to put elevator back in service	FY15
P790410	\$ 135,515.00	O'Quinn Law Library Strobes	State Fire Marshall finding concerning lack of audio/visual devices and strobes	FY15
P790411				
P790412	\$ 140,000.00	MDA Library West Façade repair	Walls adjacent to the Faculty Senate offices are continually leaking and causing interior damage	FY15

MPEC projects approved in FY16

Project Number	Amount	Project name	Project Description	MPEC Contingency
November				
P779880 Increase	\$ 35,000.00	Hilton Landscaping in South Patio	Replacing trees and required irrigation	FY13/FY14
P790389 Increase	\$ 8,173.50	Welcome Center Compressor replacement	Replace Damaged compressor and Sensors on Welcome Center Chiller	FY15
P790413	\$ 40,000.00	MDA Library Faculty Senate Roof Repair	Provide infrared scan and design to cap approx. 3,000 sq. ft. of roof	FY15
P790414	\$ 12,500.00	Welcome Center Paver and Ramp issues	Two concrete ramps had subsided creating a trip hazard and accessibility issue	FY15
P790415	\$ 12,000.00	Krost Hall Window glazing and caulking	All of the window seals are gone and needs to be wet glazed	FY15
P790416	\$ 24,787.99	Central Plant Disconnect Switch Replacements	Two disconnect switches for chilled water pumps no longer operate and need to be replaced	FY08
P790417	\$ 42,000.00	Elevator Controller Change Out Project	Issues with Elevator machine brakes discovered during controller change out process	FY14
P790418	\$ 1,133.45	Emergency Support for Cougar 1 feeder pole replacement	To pump water out of the manhole adjacent to Cougar 1 feeder pole	FY08
P790419	\$ 2,814.23	Biomedical Chiller Grounding	Install Grounding from all three Chillers in the mechanical room at Health and Biomed	FY08
P779999 Increase	\$ 31,843.20	Farish Hall Restroom Renovation	Replacement of Sanitary piping	FY13
P790387 Increase	\$ 18,792.00	Fleming Loading Dock and pedestrian walk	Additional funding needed to capture the survey cost in the design	FY14

MPEC projects approved in FY16

Project Number	Amount	Project name	Project Description	MPEC Contingency
December				
P790420	\$ 81,037.00	5 Replacement of 4 Cougar Feeder 1 poles on Spur	Due to rapid Deterioration of 4 feeder poles they have begun to lean and need replaced	FY12
P790423	\$ 309,865.00	Optometry Piping	Demo two old chillers at JD Armistead and tie into the Biomed Central Plant	FY16
P790424	\$ 49,000.00	Northeast Campus Sidewalk Repairs	Several portions of sidewalk were noted as ADA issues to be repaired	FY14
P790425	\$ 39,115.32	Chiller 2A Refrigerant and Oil Change	Repair Oil Cooler leak and replace refrigerant	FY14
P790426	\$ 26,188.36	Chiller #3 Refrigerant Valve Replacements	Remove and store 19,000 pounds of refrigerant and replace leaking valves	FY14
P790427	\$ 3,857.00	Cameron Grease Trap	Grease Trap has deteriorated causing sewer line back up	FY14

MPEC projects approved in FY16

Project Number	Amount	Project name	Project Description	MPEC Contingency
January				
P790428	\$ 17,500.00	PGH Room 116A HVAC Design	Phase 1 design computer room HVAC system for future expansion	FY14
P790429	\$ 25,000.00	Organ Recital Hall - Design Services	Design Services to locate source of water infiltration in Organ Recital hall	FY14
P790430	\$ 28,000.00	Agnes Arnold Room 2 Water Intrusion	Investigative inspections on water intrusions	FY11

MPEC projects approved in FY16

Project Number	Amount	Project name	Project Description	MPEC Contingency
February				
P790431	\$ 450,000.00	Agnes Arnold AHU Replacement	Replacement of 3 AHU's in Agnes Arnold Hall	FY16
P790432	\$ 2,527.57	Engineering Bldg. Emergency Water Leak	Emergency repair on 6" ductile Iron Line leading to Engineering Building	FY07
P790433	\$ 10,253.59	Emergency Water Leak by Calhoun Street	Leak identified on domestic underground pipe by Calhoun Street	FY08
P790434	\$ 12,872.64	Emergency Water Leaks by Entrance 14	Two leaks were identified and fixed at Entrance 14 between Fleming and Old Science	FY08
P790435	\$ 500,000.00	Farish Hall AHU Replacement	Replace existing Air Handling Units in Farish Hall	FY16
P790436	\$ 23,271.09	Water Damage at Fire Marshall's Office	Remove water damaged materials and repair water intrusion	FY08
P790437	\$ 193,000.00	Fleming Envelope Repair	Fleming Foundation Assembly Study, Roof and Envelope Repair	FY16
P790438	\$ 843,000.00	Hilton Re-roof Design & Construction	Existing roof has been extended beyond useful life and has several penetrations. 52% of the total cost	FY16
P790439				
P779931 Increase	\$ 900,000.00	Architecture HVAC Controls Upgrade	Provide new HVAC controls for College of Architecture	FY16
P779440	\$ 719,000.00	Moore's School of Music Roof and envelope repair	Existing roof has been extended beyond useful life and has several penetrations.	FY16
P790120 increase	\$ 500,000.00	SR1 Exterior Façade and Structural Repairs	Phase 2 of Façade Repair	FY16
P790428 Increase	\$ 846.48	PGH Room 116A HVAC Design	Phase 1 design computer room HVAC system for future expansion	FY14
P790441	\$ 10,000.00	MD Anderson Coping Stone Repair	Remove and replace damaged shell stone roof caps on roof level	FY11
P790442	\$ 21,458.11	Hilton Exterior Signage Replacement	Remove and dispose of existing sign and replace with new sign incorporating UH logo	FY11
P790443	\$ 49,000.00	E. Cullen Suite 31 ground floor water intrusion	Ground floor is experiencing water infiltration in several areas	FY11
P790343 Increase	\$ 450,000.00	Campus Wide wayfinding	Campus wide signage projects	FY16
P790444	\$ 8,208.64	Central Plant Chiller 7 Refrigerant Leak	Refrigerant valve is leaking and must be repaired	FY08
P790445	\$ 10,725.57	Central Plant Chiller #4 Actuator Replacement	Actuator is operating erratically and must be replaced	FY08

MPEC projects approved in FY16

Project Number	Amount	Project name	Project Description	MPEC Contingency
P790446	\$ 13,986.70	Chilled Water Pump 9 Motor	Repair to faulty 350HP electric motor	FY08
P790337 Increase	\$ 600,000.00	Campus Wide Access Control	FY16 portion of Campus Wide Access Control Project	FY16
P790389 Increase	\$ 16,991.14	Welcome Center Compressor replacement	Replace Damaged compressor and Sensors on Welcome Center	FY15
		Emergency Roof repair Hilton Waldorf Astoria	Chiller	
P790447	\$ 41,381.54	Ballroom	Sever leak discovered in roof of the ballroom. 52% of cost	FY11
			Provide Diagnostic Review and Study to determine best solution for	
P790448	\$ 5,000.00	TLC^2 HVAC Controls	Temperature and Humidity Control	FY15
P790449	\$ 6,121.50	Central Plant Refrigerant Conversion Study	Study to determine feasibility of Converting Chiller #3 to an	FY08
			alternative refrigerant	
P790450	\$ 23,500.00	MD Anderson Header Stone repair	Remove and replace damaged header stone located at loading	FY11
			dock	

MPEC projects approved in FY16

Project Number	Amount	Project name	Project Description	MPEC Contingency
March				
P790451	\$ 40,000.00	E. Cullen Electrical Upgrades	Building is nearing Electrical Load Capacity and this will help upcoming renovations	FY11
P790452	\$ 12,211.43	Hilton Fire Rating Controls repairs	52% of total cost	FY11
P790453	\$ 8,060.00	Hilton Paver Repair study	Circular drive is showing signs of subsidence. 52% of cost.	FY11
P790304 Increase	\$ 2,002.50	SR1 Toxic Gas Monitoring Design		FY14
P790338 Increase	\$ 114,000.00	Fleming Heat Exchanger Replacement	Equipment is beyond useful life and needs replaced	FY14
P790454	\$ 3,518.65	Fine Arts Mold Remediations	Remediation of mold growth in Fine Arts Rm 418	FY08
P790455	\$ 16,960.00	Old Science Renovation Feasibility Study	Study of Building envelope to identify renovation design challenges	FY10

MPEC projects approved in FY16

Project Number	Amount	Project name	Project Description	MPEC Contingency
April				
P790456	\$ 20,000.00	JD Armistead Flooring and Abatement	Once section of 2nd Floor Hallway is in need of flooring replacement and abatement since ACM is present	FY11
P790399 Increase	\$ 982.02	Wortham Theater Heat Exchanger replacement	Increase of Budget to cover Shop Charges	FY15
P790456	\$ 49,450.00	Central Plant optimization Study	Study of energy consumption through central plant to find efficiencies. Remove old filtration system and replace with simple circulation system	FY11
P790458	\$ 17,314.98	Koi Pond Renovation	Replace Sump line system	FY11
P790459	\$ 18,100.14	South Park Annex Sump Line	Install new overhead pull box for electrical conduit to prevent water penetrations	FY11
P790460	\$ 24,084.00	Agnes Arnold Conduit	Consultant to perform Geo-Tech and Structural Analysis with Construction Documentation	FY11
P790461	\$ 50,000.00	E. Cullen Retaining Wall	Removal of existing plant at NE area of Hilton to reduce weight above entrance to parking garage. 52/48 split funding	FY13
P790462	\$ 37,960.00	Hilton Planter Removal	Replace window sealants as per new master specs to prevent water infiltration	FY12
P790463	\$ 24,000.00	FY12 Farish Hall Window Glazing		FY12
P790464	\$ 21,200.00	Farish Hall 3rd Floor Restroom Design Services	A&E services for renovation of restrooms to meet TAS	FY14

MPEC projects approved in FY16

Project Number	Amount	Project name	Project Description	MPEC Contingency
May				
P790465	\$ 80,221.00	E. Cullen Switch Replacement	Replace 15kv ATS Switch at E. Cullen	FY13
P790466	\$ 41,118.00	E. Cullen Mechanical Upgrades	Upgrade existing HVAC system.	FY12
P790467	\$ 6,100.00	General Services Building Roof Leaks	Consultant to analyze the existing roof component	FY12
P790468	\$ 49,980.74	UHPD Fueling Station	Reactivate existing fueling station	FY11
P790469	\$ 28,899.63	Coastal Center Septic System Replacement	Design and install new septic tank	FY12
P790451 increase	\$ 21,857.20	E. Cullen Electrical Upgrades	Install two new panels in suites 22 & 23	FY11
P790375 increase	\$ 27,004.89	MD Anderson Dry Out	As Part of Haakon Unit replacement project dehumidification was needed to prevent mold outbreak	FY15